

Inspection report	Inspection Number		Ī
THIS DOCUMENT IS NON-NEGOTIABLE	Report Date	Page 1 of 44	l

A- GENERAL INFORMATION

From	TTS	Client Name:	
Contact:	Robin Huang	Contact:	-
Tel/Fax:	0086-592-5219 260	Tel/Fax:	-
E-mail	Inspection@tts-global.net	E-mail:	-
Inspector(s)	Aron Shen	Cc:	-
Supplier		Product Description	Recliner comer sofa with console chaise
Factory Name:		el/dzeli)	
Inspection Location:		Lifestyle Lifestyle	
Item No.:			
PO No.:			tion also
Inspection Performed	Final Random Inspection	Inspection Date	
Approval By	Robin Huang- Dep	t. Manager	

B- INSPECTION RESULT SUMMARY

Check Point / Result	PASSED	FAILED	PENDING	N/A	REMARK
Quantity (section D)	X				
Conformity (section E)			X		Remark 1
Workmanship (section F)			X		Remark 2
Special Test (section G)	X				
Packaging (section H)		X			Remark 3
OVERALL CONCLUSION (Client has the final decision to Reject or Approve)	Pending, due to remark 1 to 3				

Inspector's sign:	Aron Shen	Factory representative's sign:	Jack Chen
-------------------	-----------	--------------------------------	-----------

C- REMARKS:

1. For conformity check
No approval samples/color swatches were provided by client for compare when inspection. Please see enclosed photos for actual finding.



Inspection report	Inspection Number		ſ
THIS DOCUMENT IS NON-NEGOTIABLE	Report Date	Page 2 of 44	

2. For workmanship check:

Please see section F-workmanship table for actual defects finding and confirm.

3. For packing check:

For PO: HASL01-4 and item: HF - 11 and style: two-seater; the Chaise in Left pattern was packed into the Chaise in right pattern carton. And the Chaise in right pattern was packed into the Chaise in left pattern carton. It need rework them.

Note

1. 100% finished and 100% packed into cartons when inspection.

D- QUANTITY

P.O. No./ Brand		Order Quantity		ment ntity	Units Packed in Cartons		Units Finished Not Packed		Units Not Finished		
	Product No	<u>Unit</u>	<u>Unit</u>	<u>Ctns</u>	Quantity	Qty	<u>%</u>	<u>Qty</u>	<u>%</u>	<u>Qty</u>	<u>%</u>
	HF-11 L	5	9	18	1set	3pcs	12.5	0	0	0	0
HASL01-4	HF-11 R	4	9	18	1set	3pcs	12.5	0	0	0	0
HASLU1-4	HF-13 R	5	9	18	1set	3pcs	12.5	0	0	0	0
	HF-13 L	4	9	18	1set	3pcs	12.5	0	0	0	0
	HF-11 L	5	9	18	1set	3pcs	12.5	0	0	0	0
HATF01-4	HF-11 R	4	9	18	1set	3pcs	12.5	0	0	0	0
11A1101-4	HF-13 R	5	9	18	1set	3pcs	12.5	0	0	0	0
	HF-13 L	4	9	18	1set	3pcs	12.5	0	0	0	0
Total:	===	36	72	144	8sets	24pcs	100	0	0	0	0
List of CTN No.#	Lotal /4 Cartons for sampling to inspection. Carton No.										
Result	Pass										

E- PRODUCT DESCRIPTION, STYLE, COLOR CONFORMITY

	CHECK POINTS	RESULT	COMMENTS
1	Against product information on PO	Pass	
2	Against product Specifications/Drawings/Photos	Pass	
3	Against submitted Samples/Color Swatch	Pending	No reference samples/ swatch provided for reference when inspection. (Remark 1)
4.	Against instruction manual/ other information on packaging/ product.	Pass	

F- WORKMANSHIP

Inspection Standard:	ANSI/ASQ Z1.4 (
Inspection Level - Workmanship / Visual:	Fixed sample size	AQL - Critical Defectives:	Not allowed
Sampling Plan - Workmanship / Visual:	Single / Normal	AQL - Major Defectives:	2.5



Inspection report	Inspection Number	
THIS DOCUMENT IS NON-NEGOTIABLE	Report Date	Page 3 of 44

Sample Size – Workmanship / Visual:		8sets (16pcs)	AQL - Minor Defecti	AQL - Minor Defectives:		4.0	
Item/ Color	S/S		Defective Descri	ption	Critical	Major	Minor
HF-11 L	2sets (4pcs)	Lack glue			0	1	0
HF-11 R	2sets (4pcs)	Untrimmed th	read end		0	0	2
HF-13 L	2sets (4pcs)	No defect four	nd		0	0	0
HF-13 R	2sets (4pcs)	No defect four	nd		0	0	0
				Total Found:	0	1	2
				Accept:	-	-	-
	Result: Pending, due to above fi (remark 2)						

Note: A <u>Defective</u> is defined as a unit of product that contains one or more defects. A <u>Defect</u> is defined as any non-conformance of the inspected unit of product with specified requirements. A single defect is taken into account per each defective unit, in every case the most serious defect exhibited by the individual sample being inspected <u>regardless of the characteristic.</u>

G- SPECIAL TEST

	CHECK POINTS	5	FINDINGS	RESULT
1.	Description	Barcode scan test	No failure	Passed
	Sample Size:	2pcs/item		
Test method/ Accepted Standard: S		epted Standard:	Scanned & correct.	1
2.	Description	Carton drop test	No failure	N/A
	Sample Size:	1ctn for the max weight		
	Test method/ Acce	epted Standard:	XX height/8times	1
3.	Description	Unit dimension and weight	Refer to table G-1	D 1
	Sample Size: 1units/item			Passed
	Test method/ Accepted Standard:		With rule and scale	1
4.	Description	Stitches density check	Closed to client's inspection requirement:	
	Sample Size:	Full sample size	- There must be 7mm. To 10mm. From the stitching line to the end of the piece of fabric or leather used. (Actual 7mm per stitch for all items)	Passed
	Test method/ Accepted Standard:		On a flat ground	1
5.	Description	Moisture Test (for wooden item including slats)	HF-11 L:13%/10% -11 R:10%/11%	Passed
	Sample Size:	1set or 2 sets per item	-13 L: 11%/10% -13 R:7%/9%	
	Test method/ Acce	epted Standard:	With moisture tester	1
6.	Description	Practical test	OK	Passed
	Sample Size:	1 or 2 set per item		
	Test method/ Accepted Standard:		According to client's inspection requirement:	1
7.	Description	Static loading	No failure	Passed



Inspection report	Inspection Number	
Inspection report THIS DOCUMENT IS NON-NEGOTIABLE	Report Date	Page 4 of 44

	Sample Size:	1set per item		
	Test method/ Accepted Standard:		Rating power:XXX W	
8.	Sample Size: 1set per item		Please refer to G-1 table below for actual finding	Pending
			- (Remark	_
			With rule and scale	
9.	Description Internal check		The factory does not agree to open inside the sofa	Pending
	Sample Size:			
	Test method/ Accepted Standard:		No peel off after test	
	Sample Size:			
	Test method/ Acce	pted Standard:		

G-1 Measurement table

G-1 Measurement table								
Point Requirement		Sample 1 Sample 2		Unit				
HF-11 L				·				
Product size L*W*H (Seat)	178x97x101	177x96.5x100	-	cm				
Product weight (Seat)		57	-	kgs				
Product size L*W*H (Chaise)	158x80x101	158.8x79.8x100	-	cm				
Product weight (Chaise)	-	32.3	-	kgs				
HF-11 R		·						
Product size L*W*H (Seat)	178x97x101	177.8x97x100.5	-	cm				
Product weight (Seat)		57.5	-	kgs				
Product size L*W*H (Chaise)	158x80x101	158x80x100	-	cm				
Product weight (Chaise)		32.1	-	kgs				
HF-13 L								
Product size L*W*H (Seat)	178x97x101	177.5x97x100.5	-	cm				
Product weight (Seat)		57.5	-	kgs				
Product size L*W*H (Chaise)	158x80x101	157.7x80.3x100	-	cm				
Product weight (Chaise)		32.7	-	kgs				
HF-13 R								
Product size L*W*H (Seat)	178x97x101	178x97.5x100.2	-	cm				
Product weight (Seat)		57.6	-	kgs				
Product size L*W*H (Chaise)	158x80x101	157.8x80x100	-	cm				



Inspection report		Inspection Number		
THIS DOCUMENT IS NON-		Report Date		Page 5 of 44
Product weight	-	32.8	-	kgs


H- PACKAGING:

(Chaise)

1.Carton measure										
1.Carton incasure	Quantity per case	Size of case				Weight of case (Kgs)				
Item/Carton type		Length	Width	Height	Length	Actual Width	Height	Spec. (± 10%)	Actual	Remark
HF-11 L /Carton	1	(cm)	(cm) /	(cm) /	(cm)	(cm)	(cm)	/	89.3	
HF-11 R /Carton	1	/	/	/	/	/	/	/	89.6	
HF-13 L /Carton	1	/	/	/	/	/	/	/	90.2	
HF-13 R /Carton	1	/	/	/	/	/	/	/	90.4	
2.Assortment							•	•		
		. of Cartor Failed	ıs	Findings / Comments						Result
2cartons/item		0	0 No failure					Passed		
3.Packing method										
1.Client has not weight requirements										
Result:	Pending									

I- SAMPLE TAKEN:

N/A			



Cartons stacking

Inspection Number
Report Date
Page 6 of 44




The above reflects our findings at the time and place of inspection based on random selected samples in accordance with a previously agreed random statistical sampling standards. This report/certificate does not discharge or release sellers/suppliers from their commercial, legal or contractual obligations with regard to quality/quantity of delivery nor does it prejudice the buyer's right of claim toward sellers/suppliers for compensation for any found and/or hidden defects not detected during our random inspection or occurring thereafter. The report/certificate does not evidence shipment.

Version: REP-EE/HL-02


6.

Opened carton



 Inspection Number

 Report Date
 Page 7 of 44






Page 8 of 44 **Report Date**






Inspection Number
Report Date
Page 9 of 44






Inspection Number
Report Date
Page 10 of 44






Inspection Number
Report Date
Page 11 of 44





Inspection Number
Report Date
Page 12 of 44





Inspection Number
Report Date
Page 13 of 44






Inspection Number
Report Date
Page 14 of 44






Inspection Number
Report Date
Page 15 of 44





Inspection Number
Report Date
Page 16 of 44






Inspection Number
Report Date

Page 17 of 44





67. Weight measurement



68. Weight measurement

N/A

69. Defect: Lack glue-Major


70.





71. Cartons stacking

72. Opened carton




Inspection report
THIS DOCUMENT IS NON-NEGOTIABLE

Inspection Number
Report Date


Page 18 of 44





Inspection report
THIS DOCUMENT IS NON-NEGOTIABLE
Inspection Number
Report Date
Page 19 of 44






Inspection Number
Report Date
Page 20 of 44






Inspection Number
Report Date
Page 21 of 44





Inspection Number
Report Date
Page 22 of 44





Inspection Number
Report Date
Page 23 of 44





Inspection report
THIS DOCUMENT IS NON-NEGOTIABLE

Inspection Number
Report Date

Page 24 of 44






Inspection Number
Report Date
Page 25 of 44






Inspection Number
Report Date
Page 26 of 44







Inspection Number
Report Date
Page 27 of 44





Inspection Number
Report Date
Page 28 of 44






Inspection Number
Report Date
Page 29 of 44





Inspection Number
Report Date
Page 30 of 44






Inspection Number
Report Date
Page 31 of 44






Inspection NumberReport DatePage 32 of 44






Inspection Number
Report Date
Page 33 of 44





Inspection Number
Report Date
Page 34 of 44





179. Cartons stacking


Inspection Number
Report Date
Page 35 of 44



The above reflects our findings at the time and place of inspection based on random selected samples in accordance with a previously agreed random statistical sampling standards. This report/certificate does not discharge or release sellers/suppliers from their commercial, legal or contractual obligations with regard to quality/quantity of delivery nor does it prejudice the buyer's right of claim toward sellers/suppliers for compensation for any found and/or hidden defects not detected during our random inspection or occurring thereafter. The report/certificate does not evidence shipment.

Version: REP-EE/HL-02

180. Opened carton




Inspection Number
Report Date
Page 36 of 44






Inspection Number
Report Date
Page 37 of 44






Inspection Number
Report Date
Page 38 of 44






Inspection Number
Report Date
Page 39 of 44





Inspection Number
Report Date
Page 40 of 44






Inspection Number
Report Date
Page 41 of 44







Inspection Number
Report Date
Page 42 of 44





Inspection Number
Report Date
Page 43 of 44





Inspection Number
Report Date
Page 44 of 44





229. Weight measurement

230. Weight measurement

*******END************************