

| Inspection report | Inspection Number | |
|---------------------------------|-------------------|--------------|
| THIS DOCUMENT IS NON-NEGOTIABLE | Report Date | Page 1 of 22 |

A- GENERAL INFORMATION


| From | TTS | Client name: | |
|----------------------|---------------------------|---------------------|------------|
| Contact: | Robin Huang | Contact: | |
| Tel/Fax: | 0086-592-5219 260 | Tel/Fax: | |
| E-mail | Inspection@tts-global.net | E-mail: | |
| Inspector(s) | Damon Yang | Cc: | |
| | | ı | |
| Supplier | | Product description | Steel Coil |
| Factory name: | | | |
| Inspection location: | | | |
| Item No.: | | | |
| PO No.: | | | |
| Inspection performed | Final Random Inspection | Inspection Date | |

B-INSPECTION RESULT SUMMARY

| | PASSED | FAILED | PENDING | N/A | REMARK |
|---|-----------------------------|--------|---------|-----|--------|
| Quantity (section D) | | | X | | 1 |
| Product Description/Style/Color (section E) | | | X | | 2 |
| Workmanship (section F) | | | X | | 3 |
| Special Test (section G) | | | X | | 4 |
| Packaging (section H) | X | | | | |
| OVERALL CONCLUSION | Pending, due to remarks 1-4 | | | | |

C-REMARKS:

1. As per the factory actual weight list for each rolls, found the actual weight was not match to the PO information for all items, especially for item: GPY35020250693, only 78.43MT was available, instead of the PO request (125MT). And for item GPY5L02025693,no any finished product was available during inspection. Please see section D for detail finding.



| Inspection report | Inspection Number | |
|---------------------------------|-------------------|--------------|
| THIS DOCUMENT IS NON-NEGOTIABLE | Report Date | Page 2 of 22 |

2. Approval samples/swatch were provided during this inspection, For item: GPY5L020251160, the approval sample was slight darker shade than the mass cargo, refer to the photos for actually findings.



For item: GPY5L020251160

- 3. Some of inspected rolls found the scratch mark on roll surface, please see section F and photos for actual finding.
- 4. Factory did not provide the test equipment to do lead content check when inspection. And for the dimension measurement, found the actual measure result were not full same as specification, please see enclosed table G-1 for detail.
- 5. The MTC document was not provided when inspection.

D-QUANTITY

| P.O. No./ Brand | Item/Style/ | Order Quantity | Shipment Quantity | | Inspection | Units Packed in Rolls | | Units Finished Not Packed | | Units Not Finished | |
|-------------------------|---|-------------------|----------------------|-------|------------|-----------------------|----------|---------------------------|----------|-----------------------|----------|
| | Product No | <u>Unit</u> | <u>Unit</u> | Rolls | Quantity | Rolls | <u>%</u> | <u>Qty</u> | <u>%</u> | <u>Qty</u> | <u>%</u> |
| | GPY35020250693 | 125 | 78.43 | 27 | 78.43 | 78.43 | 62.74 | 0 | 0 | / | 37.26 |
| 206123 | GPY35020251160 | 25 | 29 | 9 | 29 | 29 | 100 | 0 | 0 | 0 | 0 |
| 200123 | GPY5L02025693 | 175 | 0 | / | 0 | 0 | 0 | 0 | 0 | 175 | 100 |
| | GPY5L020251160 | 25 | 29.1 | 9 | 29.1 | 29.1 | 100 | 0 | 0 | 0 | 0 |
| Total: | === | 350 | 136.53 | / | 136.53 | - | ı | 0 | 0 | - | - |
| List of Roll No.# | Total 9 Rolls for sampling to inspection. Roll No. as below: GPY35020250693:C101347A / C101348A/ C101338A. GPY35020251160:C100885C / C100886A / C100886C GPY5L02025693: N/A GPY5L020251160:C100889C / C100888C / C100889B | | | | | | | | | | |
| Result | Pending, due to rem | ark 1 | | | | | | | | | |

E-PRODUCT DESCRIPTION, STYLE, COLOR CONFORMITY

| I | | CHECK POINTS | RESULT | COMMENTS |
|---|---|-----------------------------------|--------|--|
| | 1 | Against product information on PO | N/A | No PO provided for checking when inspection. |



| | • | |
|---------------------------------|-------------------|--------------|
| Inspection report | Inspection Number | |
| THIS DOCUMENT IS NON-NEGOTIABLE | Report Date | Page 3 of 22 |

| 2 | Against product Specifications/Drawings/Photos | Conform | - |
|----|--|---------|-------------------|
| 3 | Against submitted Samples/Color Swatch | Pending | Refer to remark 2 |
| 4. | Against instruction manual/ other information on packaging/ product. | Conform | - |

F-WORKMANSHIP

| Inspection Standard: | ANSI/ASQ Z1.4 (| | |
|--|-----------------|----------------------------|-------------|
| Inspection Level - Workmanship / Visual: | Fixed S/S | AQL - Critical Defectives: | Not allowed |
| Sampling Plan - Workmanship / Visual: | Single / Normal | AQL - Major Defectives: | / |
| Sample Size – Workmanship / Visual: | 9rolls | AQL - Minor Defectives: | / |
| | | | |

| Item/ Color | S/S (roll) | Defective Description | | Critical | Major | Minor | |
|-----------------|--------------------|-----------------------|-------------------------|----------|-------|-------|---|
| GPY35020250693 | 3 | Scratch | Scratch mark on surface | | 0 | 0 | 1 |
| GPY35020251160 | 3 | Scratch | Scratch mark on surface | | | 0 | 1 |
| GPY5L020251160 | 3 | Scratch | Scratch mark on surface | | | 0 | 1 |
| | Total Found: 0 0 3 | | | | | 3 | |
| | | | | Accept: | 0 | / | / |
| Result: Pending | | | | | | | |

Note: A <u>Defective</u> is defined as a unit of product that contains one or more defects. A <u>Defect</u> is defined as any non-conformance of the inspected unit of product with specified requirements. A single defect is taken into account per each defective unit, in every case the most serious defect exhibited by the individual sample being inspected <u>regardless of the characteristic.</u>

G-SPECIAL TEST

| | CHECK POINTS | | FINDINGS | RESULT |
|----|---|--|---|---------|
| 1. | Description Bending suitability testSample Size: 3pcs/item | | GPY35020250693: passed GPY35020251160: passed | Pass |
| | | | GPY5L020251160: passed GPY5L02025693: N/A GPY5L020251160:passed | |
| | Test method/ Accepted Standard: | | 1T | |
| 2. | Description Unit dimension and weight | | Refer to below table for actual finding | Pending |
| | Sample Size: 3pcs/item | | | |
| | Test method/ Accepted Standard: | | With rule and scale | |

G-1: Measurement

| Item: GPY35020250693 | Specification | Roll No: C101347A | Roll No: C101348A | Roll No: C101338A |
|-------------------------|---------------|-------------------|-------------------|-------------------|
| Length | 693mm | 695mm | 694mm | 695mm |
| Thickness | 0.25mm | 0.251mm | 0.254mm | 0.255mm |
| Weight | ≤3500kg | 3030kg | 2.550kg | 3.07kg |
| Top paint | 25 MICRONS | 25MICRONS | 26MICRONS | 25MICRONS |



| Inspection report | Inspection Number | |
|---------------------------------|-------------------|--------------|
| THIS DOCUMENT IS NON-NEGOTIABLE | Report Date | Page 4 of 22 |

| Bottom Paint | 5 - 7 MICRONS | 12MICRONS | 10MICRONS | 10MICRONS |
|-------------------------|---------------|-------------------|-------------------|-------------------|
| Aperture size | 508mm | 504mm | 505mm | 505mm |
| Item: | Specification | Roll No: C100885C | Roll No: C100886A | Roll No: C100886C |
| GPY35020251160 | 11(0, | 11(0 | 11(0, | 11(0 |
| Length | 1160mm | 1160mm | 1160mm | 1160mm |
| Thickness | 0.25mm | 0.250mm | 0.247mm | 0.244mm |
| Weight | ≤3500kg | 3320kg | 2700kg | 2920kg |
| Top paint | 25 MICRONS | 26 MICRONS | 26 MICRONS | 25 MICRONS |
| Bottom Paint | 5 - 7 MICRONS | 12MICRONS | 11MICRONS | 10MICRONS |
| Aperture size | 508mm | 505mm | 504mm | 505mm |
| Item: GPY5L020251160 | Specification | Roll No: C100889C | Roll No: C100888C | Roll No: C100889B |
| Length | 1160mm | 1162mm | 1160mm | 1161mm |
| Thickness | 0.25mm | 0.244mm | 0.243mm | 0.243mm |
| Weight | ≤3500kg | 3270kg | 3360kg | 3230kg |
| Top paint | 25 MICRONS | 25MICRONS | 26MICRONS | 25MICRONS |
| Bottom Paint | 5 - 7 MICRONS | 10MICRONS | 11MICRONS | 10MICRONS |
| Aperture size | 508mm | 506mm | 507mm | 506mm |

H- PACKAGING:

| 1.carton size | | | | | | | | |
|---------------------------|--------------|--------------------------|------------|-------------|--------------|---------------------|-----------------|--------|
| Carton | Quantity | Length (cm) | Width (cm) | Height (cm) | Other | Client Tolerance | Weight (Kgs) | Remark |
| Export (actual) | - | - | - | - | - | - | - | - |
| 2.Assortment | 2.Assortment | | | | | | | |
| No. of Cartons Checked | N | lo. of Cartons Failed | | Fir | ndings / Cor | nments | | Result |
| N/A | | 0 | | No failure | | | | |
| | | | | | | | | |

3.Packing method

Packing: Each roll was covered by paper, then bundled with steel strips. Then an information label (Item name +Standard+ Length+ Specification +Item No +Weight+ Material +Grade +Production data +Colour+ Inspector+ Factory information on the label) was stuck on the side of roll surface. On the wooden pallet packaging.

| Shipping mark (1) sides | Side mark (1)sides | Inner marking ()sides | Others |
|-------------------------|--------------------|-----------------------|--------|
| See photos | See photos | N/A | N/A |
| | | | |
| Result: Pending | | | |

I- SAMPLE TAKEN:

TTS
-Testing Technology Service Ltd.

| Inspection report THIS DOCUMENT IS NON-NEGOTIABLE | Inspection Number | |
|---|--------------------------|--------------|
| | Report Date | Page 5 of 22 |

1pc A4 size of product for each item was cut and kept by TTS for future reference when inspection

PHOTOS





1). Packed rolls


2). Packed rolls

Item: GPY35020250693





3). Rolls view





5). Sample piece



6). Sample piece



 Inspection Number

 Report Date
 Page 6 of 22





Inspection Number
Report Date Page 7 of 22





| Inspection Number | |
|-------------------|--------------|
| Report Date | Page 8 of 22 |





| Inspection Number | |
|-------------------|--------------|
| Report Date | Page 9 of 22 |





25). Weight check

26). Weight check

Item: GPY35020251160





27). Rolls view



28). Rolls view



29). Label

30). Label



 Inspection Number

 Report Date
 Page 10 of 22





Inspection Number
Report Date
Page 11 of 22





Inspection Number
Report Date
Page 12 of 22





43). Cardboard sleeves ID check

44). Cardboard sleeves ID check





45). Weight check

46). Weight check

Item:GPY5L020251160





47). Rolls view

48). Pallets view



Inspection Number
Report Date
Page 13 of 22





| Inspection Number | |
|-------------------|---------------|
| Report Date | Page 14 of 22 |





 Inspection Number

 Report Date
 Page 15 of 22






 Inspection Number

 Report Date
 Page 16 of 22






| Inspection Number | |
|-------------------|---------------|
| Report Date | Page 17 of 22 |







| Inspection Number | |
|--------------------------|---------------|
| Report Date | Page 18 of 22 |






| Inspection Number | |
|--------------------------|---------------|
| Report Date | Page 19 of 22 |





85). Compared with approval sample

86). Compared with approval sample





87). Compared with approval sample

Others

88). Compared with approval sample





89). A4 paper size sample was picked up


90). A4 paper size sample was picked up



Inspection report
THIS DOCUMENT IS NON-NEGOTIABLE


Inspection Number
Report Date

Page 20 of 22






Inspection Number
Report Date
Page 21 of 22





98). Factory gate





99). Packing list from factory

100). Packing list from factory

| | | | 29 | 333 |
|------------|---------|----------|-------|------|
| 0. 25*1160 | RAL7016 | C100887A | 3. 17 | 1580 |
| 0.25*1160 | RAL7016 | C100887B | 3.2 | 1580 |
| 0.25*1160 | RAL7016 | C100887C | 3.41 | 1680 |
| 0.25*1160 | RAL7016 | C100888A | 3. 17 | 1560 |
| 0.25*1160 | RAL7016 | C100888B | 3. 1 | 1560 |
| 0.25*1160 | RAL7016 | C100888C | 3. 36 | 1660 |
| 0.25*1160 | RAL7016 | C100889A | 3. 19 | 1570 |
| 0.25*1160 | RAL7016 | C100889B | 3. 23 | 1600 |
| 0.25*1160 | RAL7016 | C100889C | 3. 27 | 1615 |
| | | | 29.1 | |
| 0.05+000 | DILOGGO | | | |



101). Packing list from factory

102). Packing list from factory

| Defects | |
|----------------------|--|
| Item: GPY35020250693 | |



Inspection report
THIS DOCUMENT IS NON-NEGOTIABLE

Inspection Number
Report Date

Page 22 of 22

